


2000 ZRX1100 PARTS DIAGRAM

Turn Signals



2000 ZRX1100 PARTS LIST

Turn Signals

ITEM NAME	PART NUMBER	QUANTITY
GASKET,SIGNAL LAMP (Ref # 11009)	11009-1402	4
LAMP-SIGNAL,RR (Ref # 23040)	23040-1195	2
LAMP-SIGNAL,FR (Ref # 23040A)	23040-1279	2
LENS-SIGNAL LAMP (Ref # 23048)	23048-1054	4
BRACKET-SIGNAL LAMP (Ref # 23051)	23051-1164	4
SCREW,TAPPING,3X16 (Ref # 92009)	92009-1115	8
SCREW,TAPPING,4X20 (Ref # 92009A)	92009-1304	4
NUT,FLANGED,6MM (Ref # 92015)	92015-1367	4
WASHER,SIGNAL LAMP (Ref # 92022)	92022-1672	4
BULB,12V 32CP(23W) (Ref # 92069)	92069-055	2
BULB,12V 32/3CP(23/8W) (Ref # 92069A)	92069-060	2
DAMPER,SIGNAL LAMP (Ref # 92075)	92075-1698	4